



VCO-Platine

Lock/
CH Alm
XMT
Key
A
RCV
Out
TX
In

Equip.
XMT
Line
Jack
Equip.
RCV
Line
Jack
Test
Jack

P4B
1 +15 Volt
2 N.C.
3 Audio
4 RSSI
5 Masse

P4A
1 Masse
2 RSSI
3 Audio
4 N.C.
5 +15 Volt

P6
1 3MHz
2 Masse
3 +15 Volt
4 Loop Detect
5 +5 Volt